

### Tecline and Scubatech diving masks manual.

All Tecline and Scubatech diving masks fulfil requirements of EU norm CE EN16805:2016-04, Regulation of the European Parliament and of the Council of the European Union 2016/425.

#### Warning:

All of the following information should be read with understanding prior the first usage of the mask.

Getting familiar with the information conditions safe usage of the product.

1. SCUBA diving mask allows you to see under water.
2. Mask should be put on directly before entering water or when you have just entered water.
3. For the proper usage of the mask, you should place it on your face and pull the strap onto the back of your head.
4. Next, you should adjust the strap so that the mask fits properly to your face.
5. If the mask presses the face too much, loosen the strap using the buckles.
6. It is not recommended to jump into the water and to dive with the face pointing down.
7. If the mask presses the face too much under water, you should exhale with the nose a few times.
8. In case the mask fogs out too much it is recommended to use "Sea Drops"
9. Loosen the strap to take the mask out of your face.

#### Maintenance:

1. The mask should be rinsed in fresh water after each use.
2. It is not recommended to use any chemicals to wash the mask.
3. It is recommended to dry the mask on the fresh air away from the sun and other sources of heat.
4. The mask should be stored in a dry and cool place away from oils, greases and cosmetics.

Declaration of conformity please download from product from <https://katalog.tecline.com.pl/>

Manufactured in Taiwan for:

Scubatech Sp. z o.o.  
ul. Lubieszewska 2  
72-006 Mierzyn